

Ricoh ESA Supported Devices Matrix

Java VM Card Type L - Ricoh Code 414902

Platform	Ricoh	Gestetner	Savin	Lanier
6.0X	MP 171SPF	MP 171SPF	917SPF	LD171SPF

Java VM Card Type J - Ricoh Code 404230

Platform	Ricoh	Gestetner	Savin	Lanier
5.0X	MP 6001 SP	MP 6001 SP	9060sp	LD360sp
5.0X	MP 7001 SP	MP 7001 SP	9070sp	LD370sp
5.0X	MP 8001 SP	MP 8001 SP	9080sp	LD380sp
5.0X	MP 9001 SP	MP 9001 SP	9090sp	LD390sp
5.0X	Pro 907EX	Pro 907EX	Pro 907EX	Pro 907EX
5.0X	Pro 1107EX	Pro 1107EX	Pro 1107EX	Pro 1107EX
5.0X	Pro 1357EX	Pro 1357EX	Pro 1357EX	Pro 1357EX

Java VM Card Type I - Ricoh Code 41470

Platform	Ricoh	Gestetner	Savin	Lanier
4.1X	MP C2050	MP C2050	C9020	LD520C
4.1X	MP C2550	MP C2550	C9025	LD525C
4.1X	MP C2800	MP C2800	C2828	LD528C
4.1X	MP C3300	MP C3300	C3333	LD533C
4.1X	MP C4000	MP C4000	C4040	LD540C
4.1X	MP C5000	MP C5000	C5050	LD550C

MFP's with Fiery Controlers - Java VM Card Type I

Platform	Ricoh	Gestetner	Savin	Lanier
4.1X	MP C2800 (E-3100)	MP C2800 (E-3100)	C2828 (E-3100)	LD528C (E-3100)
4.1X	MP C3300 (E-3100)	MP C3300 (E-3100)	C3333 (E-3100)	LD533C (E-3100)
4.1X	MP C4000 (E-5100)	MP C4000 (E-5100)	C4040 (E-5100)	LD540C (E-5100)
4.1X	MP C5000 (E-5100)	MP C5000 (E-5100)	C5050 (E-5100)	LD550C (E-5100)

Java VM Card Type F - Ricoh Code 414004 - Lanier Code 2167201

Platform	Ricoh	Gestetner	Savin	Lanier
4.1X	MP 2550	MP 2550	9025	LD425
4.1X	MP 3350	MP 3350	9033	LD433
4.1X	MP 4000	MP 4000	9040	LD040
4.1X	MP 5000	MP 5000	9050	LD050
4.1X	MP C6000	MP C6000	C6055	LD260C
4.1X	MP C7500	MP C7500	C7570	LD275C
4.1X	Pro C900S	Pro C900S	Pro C900S	Pro C900S
4.1X	Pro C900S (E-80)	Pro C900S (E-80)	Pro C900S (e-80)	Pro C900S (E-80)
Java VM Card is already pre-installed on the following machines:				
4.18	MP 2851SP	MP2851SP	9228SP	LD528SP
4.18	MP 3351SP	MP 3351SP	9233SP	LD533SP
4.18	MP 4001SP	MP 4001SP	9240sp	LD140SP
4.18	MP 5001SP	MP 5001SP	9250sp	LD150SP

Java VM Card Type C - Ricoh Code 413210 - Lanier Code 4817072

Platform	Ricoh	Gestetner	Savin	Lanier
2.X	MP C2000	N/A	C2020	LD420C
2.X	MP C2500	DSc525	C2525	LD425C
2.X	MP C3000	DSc530	C3030	LD430C
2.X	MP C3500	DSc535	C3535	LD435C
2.X	MP C4500	DSc545	C4540	LD445C
2.X	MP 5500	DSm755	8055	LD255
2.X	MP 6000	MP 6000	8060	LD260
2.X	MP 6500	DSm765	8065	LD265
2.X	MP 7000	MP7000	8070	LD270
2.X	MP 7500	DSm775	8075	LD275
2.X	MP 8000	MP8000	8080	LD280
2.X	MP 9000	DSm790	8090	LD190
2.X	MP 1100	DSm7110	8110	LD1110
2.X	MP 1350	DSm7135	8135	LD1135
2.X	Pro 906EX	Pro 906EX	Pro 906EX	Pro 906EX
2.X	Pro 1106EX	Pro 1106EX	Pro 1106EX	Pro 1106EX
2.X	Pro 1356EX	Pro 1356EX	Pro 1356EX	Pro 1356EX

Java VM Card Type B - Ricoh Code 413133 - Lanier Code 4810916

Platform	Ricoh	Gestetner	Savin	Lanier
1.X	2051	DSm651	4051	LD151
1.X	2060	DSm660	4060	LD160
1.X	2075	DSm675	4075	LD175
1.X	3224C	DSc424	C2410	LD124c
1.X	3260C	DSc460	C6045	LD160c
1.X	Color 5560	CSS55	SDC555	LC155
1.X	3228C	DSc428	C2824	LD328c
1.X	3235C	DSc435	C3528	LD335c
1.X	3245C	DSc445	C4535	LD345c
1.X	480W	A080	4800WD	LW411
1.X	3035	DSm735	8035	LD235
1.X	3045	DSm745	8045	LD245
1.X	3025	DSm725	8025	LD225
1.X	3030	DSm730	8030	LD230
1.X	MP 2510	DSm725e	8025e	LD325
1.X	MP 3010	DSm730e	8030e	LD330
1.X	MP 3500	DSm735e	8035e	LD335
1.X	MP 4500	DSm745e	8045e	LD345